

MONTAGEANLEITUNG


Obergestell E 1000, 1250 und 1500mm

Assembling instructions for overhead frame

Mode d'emploi pour cadre supérieur

Multi-Wand / Multi-board / Tableau variable

Workraster



MONTAGEANLEITUNG

Obergestell E 1000, 1250 und 1500mm

Assembling instructions for overhead frame

Mode d'emploi pour cadre supérieur

Multi-Wand / Multi-board / *Tableau variable*


Workraster

Zubehör:


Accessories:

Accessoires:


1x




2x



2x



10x M6x16



8x M6x14



10x Ø6




10x M6



4x 30x30



2x



1x (optional / en option)

